



**Federal Aviation  
Administration**

# **Light Sport Aircraft Structural Safety Record**



**Prepared by Pete Devaris and Brad Wacker  
Office of Accident Investigation  
Safety Analysis Branch, AAI-220**


**July 2008**

# Light Sport Aircraft



## Fleet Summary and Accident Classification

# LSA Airworthiness Certificates



- Registered By Jan 31, 08 and Not Part 103
- Kit-Built
- Previously Issued Under 21.190 (S-LSA)



# LSA / SP Fatal Accidents FY05-08 (Jul)

(29 Fatal Accidents)

<b>Loss of Control</b>	<b>16</b>	<b>55%</b>
<b>Fuel Exhaustion</b>	<b>3</b>	<b>10%</b>
<b>In-flight Breakup</b>	<b>4</b>	<b>14%</b>
<b>Fuel Starvation</b>	<b>1</b>	<b>3%</b>
<b>Midair</b>	<b>1</b>	<b>3%</b>
<b>Missing</b>	<b>1</b>	<b>3%</b>
<b>Unknown</b>	<b>3</b>	<b>10%</b>



# LSA Structural Failure (In-flight) Fatal Accidents FY05-08

## 4 Fatal Accidents

- 2 E-LSA (home-built)
- 2 S-LSA (factory built)
- 3 of the 4 in-flight breakups involved Zenith Zodiac aircraft.
- 2 of the 3 Zenith Zodiac aircraft were factory built.
- This indicates a potential design issue specific to the Zenith Zodiac aircraft.
- There are no other known in-flight structural failures.
- In FY08-09, the FAA's Small Airplane Directorate (AIR-200) will conduct a major study of the effectiveness of ASTM Consensus Standards and manufacturer's adherence to these standards. This study is expected to be completed by July, 2009.



# LSA Structural Failure Summary

- NTSB Identification # MIA08LA105  
E-LSA Aviate Raptor (home-built)  
Still under investigation
- NTSB Identification #DFW07LA102  
E-LSA Zenith Zodiac (home-built)  
Still under investigation
- NTSB Identification #LAX07FA026  
S-LSA Zenith Zodiac (factory built)  
Still under investigation
- NTSB Identification #NYC08FA158  
S-LSA Zenith Zodiac (factory built)

**Probable Cause: Improper pre-flight planning, deteriorating weather conditions,  
resulting in Loss-of-control followed by in-flight break-up.**

